| marantz. | | Date: | 15-May2003 | Model: DR6000, DR6050, CDR631, CDR500 | |
|---|--------------|---|------------|---------------------------------------|--|
| SERVICE BULLETIN | | Page: | 1 / 1 | REF.NBR: MZ02-031 | |
| Circulation: | Application: | Subject: | | | |
| x for information customer complaint in case of service mandatory | G. D.I. | Replace the Chip capacitor on the CDR mode MAR770/MAR775. | | itor on the CDR module of | |
| | See Below | Int.ref: | | | |

[PHENOMENON]

The chip capacitor is likely to be damaged in the inconsistency of voltage proof. But, a problem symptom doesn't appear.

[SOLUTION]

The chip capacitor is changed to 0.1uF/50V on the CDR Module of MAR770/MAR775.

POS.NO.: 2725

2726 2727

Refer to the following of the service manual.

MAR770/MAR775 CDR Module (service manual part no.: 385K855020)

CDR MAIN BOARD - BOTTOM VIEW: POWER PART TESTPOINTS

CDR 3rd gen. 7. GB70 position B5

[NECESSARY PART]

DK98104300 (0.1uF/50V)

[REMARKS]

This improvement has been done in the production line after

the Lot number MZxxxxxx17xxxx and later.(DR6000)

the Lot number MZxxxxxx13xxxx and later.(DR6050)

the Lot number MZxxxxxx15xxxx and later.(CDR631)

the Lot number MZxxxxxx11xxxx and later.(CDR500)

The Lot number is mentioned the serial number label on the rear panel.

(ex.MZxxxxxx17xxxx)

| SERVICE BULLETIN | | Date: | 22-Nov-01 | Model: DR4 | 050/DR6000/DR605 CDR500/CDR631 | |
|---|--------------|--|-----------|------------|-----------------------------------|--|
| | | Page: | 1/1 | REF.NB | MZ01-019 | |
| | | Subject: | | | | |
| Circulation: | Application: | | | | | |
| x for information customer complaint in case of service | See below | Improvement for inoperable all buttons | | | | |
| mandatory | | | Int.ref: | | | |

[PHENOMENON]

While CD is played or CD-R/RW is recorded, the FL display is frozen and all buttons will not be worked. (except POWER button.)

[SOLUTION]

Replace the DASP IC **POS No.7701**> with a new one **(8204 056 03460, QC05603460).**

[REMARK]

<Application LOT number>

DR4050: 01 - 11 LOT DR6000: 01 - 16 LOT DR6050: 01 - 12 LOT CDR500: 01 - 10 LOT CDR631: 01 - 14 LOT

This improvement has been done in the production line after

the LOT number "12" and later. (DR4050)

the LOT number "17" and later. (DR6000)

the LOT number "13" and later. (DR6050)

the LOT number "11" and later. (CDR500)

the LOT number "15" and later. (CDR631)

The lot number and the service modification code are mentioned in the serial number label on the rear panel. (ex. MZxxxxxx12xxxx)

| service Bulletin | | Date: | 15-May2003 | Model: DR6050,CDR500 | |
|---|--------------|---------------------------------|------------|----------------------|--|
| | | Page: | 1 / 1 | REF.NBR: MZ02-035 | |
| | | Subject: | | | |
| Circulation: | Application: | Miss clamp problem of CD single | | | |
| x for information customer complaint in case of service mandatory | See Below | Int.ref: | : | | |


[PHENOMENON]


The OPEN/CLOSE movement of disc tray is fast, It may become a CD single [8cm(3in.)] clamp defect.

[SOLUTION]

15k ohm resistor is soldered to the Pos.No.3114 in parallel.

The object of PCB: CD MAIN BOARD of CD Module MAR1250 (Refer to the CDR500 service manual 2-13 page of MAR1250.)





[NECESSARY PART]

15k ohm GD05153160

[REMARKS]

The countermeasure apply to this claim only.

[REMARKS]

This improvement has been done in the production line as follows. the Lot number MZxxxxxx21xxxx and after.(DR6050) the Lot number MZxxxxxx26xxxx and after.(CDR500)

The Lot number is mentioned the serial number label on the rear panel. (ex.MZxxxxx21xxxx)