28-Sep-2004

marantz.		Date:	-25-Sep-2004	Model: SR5500
		Page:	1 / 2	REF.NBR: MZ04-063Revised
SERVICE BULLETIN		Subject:		
Level	Application:	Software Update Information.		
Software Update	MZ00xxxxxxxxx			
		Int.ref:		

2nd edition. The contents of Level and Subject are changed.

[PHENOMENON]

When Tuner frequency is changed in the direct key input using CRESTRON, the outside of the frequency band will be displayed.

[CONTENT]

Improvement of the RS232C Tuner command (part) specification in combination with CRESTRON system.

[SOLUTION]

The firmware was fixed.

- 1. Update the Microprocessor IC28 firmware Version to [V040831 1] Please see to the service manual page 9 about details of "6. UPDATE FIRMWARE".
- 2. Update the firmware is attached to the e-mail.

File name: SR5500_CPU_V040831_1.zip

Attention

Don't start Zip file from attached file.

Please copy on your PC and be sure to use it after defrosting.

[NECESSARY PART]

Update of the firmware CPU program disc.


Disc Part no. 90M-SR5500CDR (SR5500 CPU V040831 1.zip)


[REMARKS]

1. This problem apply to the following serial number.

SR5500/N1S	from MZ000431000001 to MZ MZ000431001588
SR5500/N1G	from MZ000431000001 to MZ MZ000431000250
SR5500/N1B	from MZ000431000001 to MZ MZ000431000950
SR5500/U1B	from MZ000434000001 to MZ MZ000434000700

2. This improvement has been done in the production service code MZ01 and after.





9. Press MULTI button again to quit this mode.