

marantz[®]

Service Bulletin

No. : MZ07-014

Date: February 9, 2007

Model: SR7001, SR8001

Subject: Software Update Information.

Symptom: 1. Originally the product was designed that if the speakers short, the unit automatically detects the error and then turns the relay on. Now, in order to improve the safety of the protective operation, once a short occurs, the product goes into standby mode instead of turning on and can only be powered on again by Main power-OFF and ON.

2. When the unit is connected to the Sony PlayStation3[®] with HDMI and plays an SACD, there is no audio output.

3. When more than 6 channels are connected in HDMI M-PCM, there is no indication of or audio output from the 7th and 8th CHs.

4. When the unit receives the command [@XDP:1] to switch over the XS DISP mode, with the XM ANTENNA unplugged, it can respond with [@XDP:2], the next number up.

5. The product may not respond to the following RS232C commands: EX/ES [@SUR:0A], THX [@THX:3] ~ [@THX:9], THX ON [@THX:2].

6. While playing back a DTS 96/24 signal, it transmits a status reply at an RS232C sampling rate of 48KHz [@SFQ:3] instead of 96KHz [@SFQ:5], which it should be.

7. When the product is connected to a Marantz LC3701[®] a Marantz PD4201[®] or a Panasonic PT-AX100[®] with HDMI, the onscreen image can be tinged with pink.

Solution: 1. The MAIN and HDMI microprocessors need to be updated. First, please check the version of each firmware and DSP code in reference to the Service Manual on Page 10 of the Service Mode.

.

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

2. Firmware and part number file content: SR8001_Main0701221_Hdmi050.zip (425KB)

a) Firmware Ver: SR8001_0701221.mot (See the Service Manual on Page 40 for the procedure.)

Parts No: 00M06CW499A03

b) Firmware Ver: HDMI_REPV2x070110h50.mot (See the Service Manual on Page 50 for the procedure.)

Parts No: 00M06CW499B04

Check the firmware version before updating. If your unit needs to be updated, please make sure to perform the latest update.

Firmware Version

Ref No	Date	MAIN	HDMI	DSP CODE (for ref)	
MZ07-014	2007. 1.22	V0701221	h50	38609041	Latest

Parts:

Ref#	Description	Part Number
NA	SR8001_0701221.mot	00M06CW499A03
NA	HDMI_REPV2x070110h50.mot	00M06CW499B04

Serial Number Range:

The update is required of the following serial numbers:

SR7001

ServiceCode: 02

* Service Code (part of aa in S/N): MZaaxxxxxxxxxx

SR8001

ServiceCode: 02

* Service Code (part of aa in S/N): MZaaxxxxxxxxxx

The following serial numbers have already been updated:

SR7001

ServiceCode: 03

* Service Code (part of aa in S/N): MZaaxxxxxxxxxx

SR8001

ServiceCode: 03

* Service Code (part of aa in S/N): MZaaxxxxxxxxxx

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.