
SERVICE HINT

PROBLEM:

Rear channels are not loud enough.

CAUSE:

As the rear speakers are connected in series, the volume is too low.

SOLUTION:

Replace resistor R 674, normally 4K7, by 12K.

This will increase the output level of the remote speakers in such a way, that the level is the same at 0dB using all 8 ohms speakers.

R674 is located behind the volume control, under IC Q674.

PRODUCTION: