
MODIFICATION

PROBLEM:

When a frequency of 10.25 MHz or higher is stored into preset 3 the unit may change this frequency to 12.8 MHz less after receiving any remote command (102MHz becomes 89.2MHz). This occurs even with other brand's remote commands.

CAUSE:

This is a software bug.

SOLUTION:

There are two possible solutions for this fault:

- The best solution is to replace the CPU, this will keep the partnumber mentioned in the service manual: LC866448B (U201)
- The fast solution is to disable the IR receiver, this is only possible if you are 100% certain the customer will not use this function.

It is advisable to perform this modification whenever a unit comes in for service.

PRODUCTION:

The new CPU will be installed from serial: G0XC42003201