



Technical Bulletin C542

Product: CD Player

Hardware Technical Bulletin: C542-H2005-04

Date: June 27/05

Subject: Improved Playability

Note: Implemented in production starting from serial #: G56C54224800

Previous T.B.'s required:

YES

NO

DESCRIPTION: *You may have the complaint that some discs are difficult to play .*

REASON: *The rf eyepattern level can be slightly lower than expected when reading some cd's.*

SOLUTION: *Increase rf level from laser pick up. Change the following parts to increase the rf level.*

- 1. Change resistor R227 from 100R to a jumper wire.*
 - 2. Change resistor R103 from 20K to 15K.*
 - 3. Change resistor R218 from 15K to 47K.*
 - 4. Change capacitor C221 from 0.1uF to 3900 pF.*
-

Contact:

NAD Electronics International

633 Granite Court

Pickering, ON Canada L1K 3K1

Voice: 905-831-0799 FAX 905-837-6357

www.nadelectronics.com