


# TX-DS797 and TX-DS898

Preparation to work or troubleshoot on DSP as well as possibly power amplifier or other input function PCB assemblies. The process will take 3 to 8 minutes.


Pre-amplifier PCB / Volume is removed to create troubleshooting access for the DSP component side.



# TX-DS797 and TX-DS898

When attempting to repair or trouble shoot DSP, Video PCB and all input PCBs, follow disassembly given below.

Disconnect P9502 connector wire (Blue) and then remove all 8 screws holding heat sink to the bottom chassis. Remove white ribbon connector from P7701A DSP side. Disconnect all speaker connectors from P6810, P6812, P6008A and P6008B. Remove secondary power connector from P6951 location found on power relay PCB assembly.





Set power amplifier on it side as seen above.



# TX-DS797 and TX-DS898


Secondary power connector from P6951 being disconnected. JL6953B and P6952A found to the right may be disconnected.




With the power amplifier set on its side, the input PCB assemblies are exposed for easy troubleshooting and repair. Individual PCB may be checked without the other. S-video may not work without the composite, but if the composite works the problem with S-video is simple to asses. Speaker relay is fully functional even though there is no audio passing through as main amp is disabled. For additional ease Tuner module and its support PCB may be removed.

# TX-DS797 and TX-DS898

DSP service mode setup conclusion




All four connectors from P6810, P6812, P6008A and P6008B are disconnected to give ease of movement for the power amplifier module.



Amplifier assembly is then lifted from back to the front to stand in its side, The blue wire from P9502 is rerouted to insure amplifier movement is simplified. P9502 must be reconnected to make sure DSP and other PCB has the necessary operating voltages. At this point DSP is exposed for troubleshooting.


# TX-DS797 and TX-DS898

P7701A connector ribbon wire also needs unplugged to accommodate the vertical pull of the Volume PCB located next to the DSP



DSP PCB

System control on front panel must remain connected via ribbon wire at P7201B




Blue connector ribbon wire from P9502 temporarily need be disconnected



# TX-DS797 and TX-DS898

P5004E, P6101A and P5003E connector wires are seen still in place. These wire need unplugged and or desoldered to remove Volume PCB NCAF-7262.



Spacer Post

Wire from P9502




Figure shows volume control completely removed

# TX-DS797 and TX-DS898

Power amplifier output signal wires to speaker terminal PCB connector terminals P6812E, P6008B, P6810D and P6008A are seen removed.

In this block area exist all inputs and output I/F PCBs. Since the main amplifier is standing on its side, All input and DSP PCBs are accessible for trouble shooting.

