

|                                          |                            |                                                      |      |
|------------------------------------------|----------------------------|------------------------------------------------------|------|
| Date<br>23.04.03                         | Ref. No.<br><b>03AH002</b> | Model<br><b>CX-LEM50, CX-LEM51, XR-EM50, XR-EM51</b> | TD   |
| Subject<br><b>Part number for "J231"</b> |                            |                                                      | IRIS |

## SYMPTOM

Page 8 of the Service Manual lists incorrect information for the headphone jack J231 on the Key Board.

## SOLUTION

The correct information for J231 is listed in the table below.

| <i>Ref.</i> | <i>Description</i> | <i>Incorrect part number</i> | <i>Correct part number</i> |
|-------------|--------------------|------------------------------|----------------------------|
| J231        | Jack, Headphone    | 87-099-816-010               | S2-3B0-292-000             |
|             |                    | U-0150-132-U                 | U-0023-247-U               |