

AIWA CO.,LTD UTSUNOMIYA FACTORY

2620, TOKUJIROU-MACHI, UTSUNOMIYA-SHI, TOCHIGI 321-21, JAPAN

SERVICE TECHNICAL INFORMATION

ONE POINT REPAIR

UTSUNOMIYA, APRIL 30, 1996

REF. NO.: SI-96-008

CUSTOMER RELATIONS & SERVICE DIV.

MODEL

LCX - 500

SUBJECT


Cassette cover does not lock

SYMPTOM:

There are cases in which the LCX - 500 cassette cover does not lock.

REMEDY

The boss of the cassette box is damaged. Replace with a modified cassette box.



Note: This modification has been made for sets produced as of February 1996.

Part No.	Part Name	Ref. No.
85-CE6-004-119	BOX, CASS	-