

aiwa

AIWA CO.,LTD
UTSUNOMIYA FACTORY

2620, TOKUJIROU-MACHI, UTSUNOMIYA-SHI, TOCHIGI 321-21, JAPAN

SERVICE TECHNICAL INFORMATION

ONE POINT REPAIR

UTSUNOMIYA, September 30, 1994
REF. NO. : SI-94-025
SERVICE ENGINEERING DIV.

MODEL : NSX-320/333/3000 U
SUBJECT : Squeaking noise occurring when fast forwarding/rewinding a tape.
SYMPTOM : A squeaking noise sometimes occurs when a tape is fast forwarded/rewinded with the volume slightly turned up.

REMEDY : Add a diode so that the muting circuit can operate when fast forwarding/rewinding a tape. This measure erases the squeaking sound at the time of MS; it does not affect the MS operations at all.

