



AIWA CO.,LTD  
UTSUNOMIYA FACTORY  
2620, TOKUJIROU-MACHI, UTSUNOMIYA-SHI, TOCHIGI 321-21, JAPAN

## SERVICE TECHNICAL INFORMATION

### ONE POINT REPAIR

UTSUNOMIYA, MAY 15, 1997  
REF. NO.: SI-97-009  
CUSTOMER RELATIONS & SERVICE DIV.

MODELS : NSX-V210 / V220 / V420 / V2100  
SUBJECT : Service manual correction and DSP IC

CONTENTS : A mistake was discovered in the NSX-V210 Series Service Manual. The following is a correction of this mistake.

[NSX-V210 EZ, K, HR / NSX-V220 EZ] •••• S/M Code No. 09-96C-173-6FP

\* An incorrect name for the CD mechanism was printed on the cover of the Service Manual.

Incorrect → 4ZP-1 BDLNM  
↓  
Correct → 4ZG-1 BDLNM

\* Refer to the 4ZG-1, A, B, Z Comprehensive Manual (Code No. 09-965-128-10T) Type [B] (models with a built-in Toshiba IC).

\* The 4ZG-1 BDLNM equipped in NSX-V210, V220, and V2100 comes with a DSP IC (IC101). TC-9441F is used in this IC, but is also compatible with TC-9284F.

Part Name	Part No.	
IC TC9284F	(87-070-336-010)	Compatible Parts
IC TC9441F	(86-NFZ-669-010)	

Note: There are sets equipped with a 4ZG-1 ZDLNM that only have NSX-V2100 (U) specifications.