

NOTES:

- I. CAUTION HIGH VOLTAGE CONTACT COULD BE LETHAL.
- 2. CAP. IN UF UNLESS NOTED.
- DENOTES CABLE CONNECTOR PIN NUMBERS.
 - DENOTES WIRE CONNECTION TO BOARD.
- 4 LEFT CHANNEL SHOWN, RIGHT CHANNEL IN PARENTHESIS WHERE DIFFERENT.
- 5. WHERE NOTED, MEASURE VOLTAGE THRU IKA RESISTOR AT TEST PROBE TIP, TO AVOID HE INSTABILITY
- 6. WHERE NOTED. "TRIM" RESISTORS MUST BE MATCHED TO INDIVIDUAL FETS OR BY FET GRADE. CONSULT FACTORY FOR REPLACEMENT.

REVISIONS

A NOV 1985 V4,5 SELECTED FOR TRANSCONDUCTANCE.

B JAN 1986 RV4 OLDER TYPES REPLACED BY P/N 45100529


MAR 1986 SWI-8 IMPROVED WITH SEALED TERMINALS, WAS P/N 24100400. R22.23.24.25 CHANGED, WAS P/N 30006410.

(SEE PARTS LIST)
MAY 1986 C49, 53 WERE 150 PF STYRENE.

E JUN 1986 C49 WAS 150 pF PPN, C50 WAS (2) 5pF STYRENE IN SERIES OR (2) 4 pF PPN IN SERIES, C52 WAS IOPF STYRENE, R92 WAS 100K 2W.

PROPRIETARY NOTICE

THIS DRAWING CONTAINS PATENTED, PATENT APPLIED FOR, AND/OR OTHER INFORMATION CONSIDERED PROPRIETARY BY AUDIO RESEARCH AND IS FURNISHED ON A CONFIDENTIAL BASIS FOR IDENTIFICATION AND REPAIR PURPOSES ONLY.







LINE SECTION

SPII PREAMP UNIT

