



4. ADDED AS SECONDARY OPERATION.
 2. ALL CAPACITORS IN MICORFARADS, EXCEPT AS NOTED.
 1. ALL RESISTORS IN OHMS
- NOTES: UNLESS OTHERWISE SPECIFIED.

CARVIN
BX600, BX1200
System Master

12340 World Trade Drive
 San Diego, CA 92128
 (858) 487-1600
 FAX 487-6629

DRAWN BY: GEORGE DREYER DATE: 30MAY05
 APPROVED: DATE:
 PCB NO: 30-42500 REV: E
 ASSY. NO: 80-42800 REV: B
 NO: 80-42122
 REVISED BY: GEORGE DREYER DATE: 11AUG06

- Changes from Assembly Rev (B).
 1. Fan high speed circuit correction.
 2. correct shorted jumpers
- Changes from Assembly Rev (C) not made.
 1. Add resistors for P5 & P8 on BR600.
 2. correct bias circuit on amp 2
- CHANGES FOR BX1200 ASSEMBLY: 80-42122
 1. Add Q110, Q210 (Type: MJL 21194).
 2. Add Q114, Q214 (Type: MJL 21193).
 3. Add R168-R175, R268-R275 (0.22%).
 4. Change C501, C502 to 10Kmf @ 80V.
- EX800 Assembly jumpers
 B401, B402, B403, B404
 B405, B406, B407, B408
- BX1200 Assembly jumpers
 B801

