

IMPORTANT NOTE

In circumstances where this receiver has not been used for a period of weeks, it is possible that a capacitor in the AUTOSCAN circuit may need 'reforming'. In some cases, when AUTOSCAN tuning is used for the first time after the receiver has been idle for some time, the unit may not tune all the way up the FM band to 108 MHz. The remedy is quite simple and does not require any outside service assistance. On models 450-T and 505-T, press the CONTINUOUS ADVANCE push-button and hold it until the AUTOSCAN meter indicates "108".

On models 500-TX and 800-T the same result can be obtained by pressing in the right-hand AUTOSCAN tuning pushbutton. In a few extreme cases, this procedure may have to be repeated several times to fully 'reform' the AUTOSCAN capacitor and produce full-range tuning.

If you have any questions, please do not hesitate to write Customer Service Department, Fisher Radio, 11-40 45th Road, Long Island City, New York 11101.