



## **Service Bulletin**

**No. :** MZ09-174

**Date:** August 6, 2010

---

**Model:** CC4003

**Subject:** Correction of the Firmware.

Countermeasure is applicable upon every repair (within S/N range) and upon customer complaint.

**Symptom:** Noise can occur momentarily while playing the Data Track of a Mixed Mode CD.

**Solution:** We corrected the MICON Software so that no malfunction occurs.  
MODIFICATION: Please refer to page 8 "**UPDATE DSP FIRMWARE PROCEDURE**" in Service Manual.

**Parts:**

Parts Number of software: **CC4003\_00M21DW499A02.zip**

**Serial Number Range:**

Please apply the above modification to the production models in the following serial numbers.

MZ\*\*\*\*\*000001 ~ MZ0010\*\*002148

---

**CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.