

**marantz®**

## **Service Bulletin**

**No. :** MZ03-058

**Date:** December 13, 2006

---


**Model:** CC4300, PMD371

**Subject:** DIGITAL Output (OPTICAL) jack was changed.

**Symptom:** The OPTICAL jack was changed by manufacturer.

**Solution:** 1) The OLD and NEW type are compatible in performance, but you cannot replace the OLD type with NEW type. (The PCB mounting hole dimension is different.)

2) The NEW type can be replaced with the OLD type.



---

### **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

**Parts:**

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
NA	Digital Optical Jack	*YT002580R	Digital Optical Jack	*YT003690R

**Serial Number Range:**

All

---

**CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.