



Service Bulletin
No. : MZ01-009
Date: November 29, 2006

Model: DR4050

Subject: Part number correction.

Symptom: The part listed in the service manual, WINDOW (003B) is not a replaceable part.

Solution: The window should be replaced together with the FRONT PANEL (002B).

Parts:

Ref#	Description	Part Number
003B	FRONT PANEL (BLACK)	435W248010
003B	FRONT PANEL (GOLD)	435W248110

Serial Number Range:
All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.