



Service Bulletin

No. : MZ08-048

Date: September 9, 2008

Model: ES7001

Subject: Change of OPT Connector

Symptom: The Optical connector shutter has been broken when the OPT cable is unplugged.

Solution: 1. To prevent the optical connector from being damaged, it has been replaced with one without a shutter. All three POS NO. JR01, JR02, JR03 (INPUT PWB P601) will be all replaced.



All the three to be replaced.


CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

Old PART NO. 00MYJ15000270



New PART NO. 643010054005S



Parts:

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
JR01, JR02, JR03	OPT. CONN.	00MYJ15000270	OPT. CONN.	643010054005S

Serial Number Range:

20000844xxxxxx and after: Have been corrected on the production line.

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.