

marantz® SERVICE BULLETIN		Date: 28-Dec-99	Model: SD4050
		Page: 1/1	REF.NB MZ99-027
Circulation:		Application:	
x for information customer complaint in case of service mandatory		Subject: Parts number correction. (L301) Int.ref:	

[PHENOMENON]

The parts number mentioned in the service manual (9965 000 01145 : *TC000330R) page 25 for L301 is not correct.

[SOLUTION]

Correct spare parts number and description are as follows;

Parts number : 9965 000 01011 (*TC000340R)
Description : SM-10F (Bias Coil)