



Service Bulletin

No. : MZ07-084

Date: September 10, 2007

Model: SR4002, SR5002

Subject: First edition software Information.

Symptom: The version Software (firmware) listed was used for the original production of the product.

Solution: Please refer to the service manual for "How to update Software".
*Flash ROM (With software). Usually, no need to write-in this software.
The replacement Flash ROM IC's have already had the software written to it.

Software Version

Micro-processor POS.NO	TYPE	VERSION	REMARK	FILE NAME of Upload on marantz S.D.I	PART NO.
IC11	CPU (Mode 2)	V070726-1	SR5002_070726_1.mot	SR5002_070726_1.zip	00M32CW499A00
IC40	DSP (Mode 1)	-	2006_12_08	SR5002_070726_1.zip	00M32CW499B00

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.