



## Service Bulletin

**No. :** MZ08-060

**Date:** October 3, 2008

**Model:** SR4023

**Subject:** Correction of the Service Manual, electrical parts list.

**Symptom:** The RELAY of MAIN PWB part number mentioned on the SR4023 Service Manual is not correct. (SR4023 Service Manual page 59)

**Solution:** See the Parts section for the new part number.

### Parts:

OLD NEW	P.W.B NAME	POS. NO.	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	MAIN	RY91	00MLY10120400	RELAY	! POWER RELAY G5PA-1 5A OMRON Factory code no. CSL1E002ZE
NEW	MAIN	RY91	943682004660S	RELAY	! RELAY G5PA-1 DC6V Factory code no. CSL1E002ZE

REMARK: The relay (00MLY10120400) used in other models does not change.

#### CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.