



Service Bulletin

No. : MZ03-009

Date: December 5, 2006

Model: SR4300

Subject: Noise from Front Left ch and/or Surround Left ch

Symptom: Noise (crackling sound) appears from front Left ch and/or the surround Left ch.

Solution: Replace CODEC IC AK4529VQ (ICS08) to new type one.

Parts:

Ref#	Description	Part Number
ICS08	CODEC IC AK4529VQ	*HC108140R

Serial Number Range:

The new IC has been applied in production after the Week code number "0250" and later. (The Week code number is the "#####" portion of the serial number "MZxx####xxxxxx".)

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.