



Service Bulletin

No. : MZ07-097

Date: October 25, 2007

Model: SR4320

Subject: Correction of the Service Manual, part no. of Sub Transformer.

Symptom: The Sub Transformer 120V/12V part number (POS. NO.T701) mentioned on the SR4320's Service Manual is incorrect. (Service Manual page 39)

Solution: Use the new part number listed when ordering a replacement sub transformer.

Parts:

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (FOR EUR)	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	T701	/U1B	nsp	*TS001870R	SUB TRANSF.	TRANSF, SUB (230V/12V) Factory code no. CLT5I001ZE
NEW	T701	/U1B	nsp	90M-TS001860R	SUB TRANSF.	TRANSF, SUB (120V/12V) SR4320/A1B Factory code no. CLT5I001ZU

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

OLD *TS001870R 230V/12V (Factory code no. CLT5I001ZE)



NEW 90M-TS001860R 120V/12V (Factory code no. CLT5I001ZU)



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.