



Service Bulletin

No. : MZ09-040

Date: August 6, 2009

Model: SR4500

Subject: Service spare part addition information.

Symptom: The part number of the Main Microprocessor software was added to Service spare part.

* The new Microprocessor needs to be updated after it has been replaced.

Solution: Download the **SR4500_PS4500_06_11_1.ZIP** file and copy it to your PC.

Attention: Don't start from a zipped file. Please be sure to unzip SR4500_PS4500_06_11_1.ZIP file before you attempt to use it.

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.