



Service Bulletin

No.: MZ08-005

Date: February 12, 2008

Model: SR4001, SR5001


Subject: Information on the addition of a Service extension cable.

Symptom: The part number of Extension FFC will be added to the Service spare parts. The PWB can now be removed from the unit and repaired.

Solution: The Extension FFC comes in several types depending on the number of PINs and the length. That is why each comes marked in the same color with the location specified on the wiring diagram (below). Please check the attached wiring diagram before use.

Parts:

Ref#	Description	Part Number
NA	EXTENSION FFC KIT	90M-ZK000800R



CONFIDENTIALITY NOTICE:

SR4001/SR5001 7. WIRING DIAGRAM UNER MODULE SR5001 [/U] Ver. VIDEO PWB KM RADIO PWB HDMI PWB AC INLET BN99 Green CN97 **Pink** INPUT PWB ULTI SPK F TRANSF. PWB BN27 **Yellow** MAIN PWB BN80 **Red** ШШ BN80 BN15 **Blue** FRONT PWB SELECTOR ENCODER PWB

POWER ON / OFF

TACT SW PWB

[/U] Ver

H/PPWB