



Service Bulletin

No.: MZ07-084

Date: September 10, 2007

Model: SR4002, SR5002

Subject: First edition software Information.

Symptom: The version Software (firmware) listed was used for the original production of the product.

Solution: Please refer to the service manual for "How to update Software". *Flash ROM (With software). Usually, no need to write-in this software. The replacement Flash ROM IC's have already had the software written to it.

Software Version

Micro- processor POS.NO	TYPE	VERSION	REMARK	FILE NAME of Upload on marantz S.D.I	PART NO.
IC11	CPU (Mode 2)	V070726-1	SR5002_070726_1.mot	SR5002_070726_1.zip	00M32CW499A00
IC40	DSP (Mode 1)	-	2006_12_08	SR5002_070726_1.zip	00M32CW499B00