



Service Bulletin

No. : MZ10-039

Date: September 15, 2010

Model: SR5005

Subject: Issuing of the initial firmware for DFW (D&M Firmware Writer).
This is Information.

Reason: Regional service needs the initial firmware.

Solution: METHOD OF UPDATE : firmware update via RS232C. We will supply the following program files for updating the subject models. Please refer to the following Instruction Manual for the updating procedure.

DFW software:

DFW_0003_SR5005_(Rev.1.0.6).exe: Firmware Update Program

DFW_0003_SR5005_Rev.1.0.6_manual_EN.pdf Instruction Manual for Firmware Update.

Firmware:

SR5005_MZ10-039.zip

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

	Name	Version
1	Main	46.55
2	Main FBL	22.13
3	Sub	28.17
4	Sub FBL	05.01
5	DSP	59.08
6	Audio PLD	A3260005
7	USB	705

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.