



D&M Holdings Inc.

100 Corporate Drive Mahwah, NJ 07430



Service Bulletin

No. : MZ03-019

Date: December 7, 2006

Model: SR5300

Subject: 1. Modify a part of the indication on display.
2. Cirrus DSP code change

Symptom: 1. Modification of item descriptions in the SETUP MAIN MENU as follows:

<u>OLD</u>		<u>NEW</u>
PL 2	-->	PLII
DTS ES	-->	DTS ES Matrix/Discrete
Neo6	-->	Neo: 6

2.The Speaker Distance problem for the center speaker delay is modified.

Solution: Replace MICRO PROCESSOR IC107 on the MAIN PCB and IC704 on the DSP PCB.MICRO PROCESSOR. After replacement the version becomes V021125 01

Parts:

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
IC107	*HC107760R	*HU100610R	*HC107760R	*HU100700R
IC704	M27W401-80B6	*HC107760R	M27W401-80B6	*HC108450R

Serial Number Range:

This improvement has been done in production as follows:
serial no.MZ010307005811 and after (SR5300/U1B).

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.