



Service Bulletin

No.: MZ08-004

Date: February 12, 2008

Model: SR6001, SR7001, SR8001


Subject: Information on the addition of Service extension cable.

Symptom: The part number of Extension FFC will be added to the Service spare parts. The PWB can now be removed from the unit and repaired.

Solution: The Extension FFC comes in several types depending on the number of PINs and the length. That is why each comes marked in the same color with the location specified on the wiring diagram (below). Please check the attached wiring diagram before use.


Parts:

Ref#	Description	Part Number
NA	EXTENSION FFC KIT	90M-ZK000790R



CONFIDENTIALITY NOTICE:

7. WIRING DIAGRAM



CONFIDENTIALITY NOTICE: