



## **Service Bulletin**

No.: MZ08-055

Date: September 30, 2008

Model: SR6003

**Subject:** Software Update.

\* This Service Bulletin is only for service information with the following minor improvement. This is <u>not</u> a call requiring a rework and there is no need to apply this update to the stock units.

**Symptom:** On the USB Status screen display, "Duration" is spelled incorrectly.

**Solution:** The MAIN CPU (Mode 1) software must be updated. First, please check the version of the current firmware in reference to SERVICE MODE of the Service Manual. After performing the update, check the indicated firmware version.

For information on how to rewrite the firmware, refer to the Service Manual "7. WRITING AND UPDATE SOFTWARE".

Firmware version History

Service Code	Service Bulletin REF.NBR	MAIN CPU	HDMI	DMP	
<b>MZ01</b>	MZ08-055	V080916 1	-	-	Latest

Please check the version of the firmware and, if any of the above is found yet to be updated, make sure to perform the latest update.

## **CONFIDENTIALITY NOTICE:**

## Parts:

Ref#	Description	Part Number
Firmware Ver	sr6003_080916_1.rom	00M08DW499A02
<ul><li>– MAIN CPU</li></ul>		
(Mode 1)		

## **Serial Number Range:**

Applies to MZ00xxxxxxxxx (Service code 00). This improvement has been done in production from serial number MZ01xxxxxxxxx (Service code 01) and after.