



D&M Holdings Inc.
100 Corporate Drive Mahwah, NJ 07430



Service Bulletin

No. : MZ09-148

Date: January 20, 2010

Model: SR6004, SR5004

Subject: Correction of the Firmware.

Countermeasure is applicable for every repair (within the S/N range) and upon customer complaint.

Symptom: The unit might switch into the "protection-mode" (Standby LED is flashing at high speed) for no apparent reason.

Solution: We corrected the MICON Software so the malfunction no longer occurs.

MODIFICATION: Please refer to page 25 "8.WRITING AND UPDATE SOFTWARE" in Service Manual.

Part Number of software:

SR5004MAIN: **SR5004_00M26DW499A02.ZIP** (Ver. V0912281)

SR6004MAIN: **SR6004_00M27DW499A02.ZIP** (Ver. V0912281)

NOTE: If the unit is target of a Service bulletin MZ09-136 (R211 mod.), please apply that countermeasure together with this MZ09-148 firmware update.

Serial Number Range:

Please apply the above modification to the production models in the following serial numbers. (Full-digit)

Model	Serial Number
SR6004	MZ*****000001 ~ MZ030951003440
SR5004	MZ*****000001 ~ MZ020951006110

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.