

marantz[®]

Service Bulletin

No. : MZ10-023

Date: August 6, 2010

Model: SR6004, SR5004

Subject: Correction of the Firmware.

Countermeasure is applicable upon every repair (within S/N range) and upon customer complaint.

Symptom: A loud noise can occur while playing the sound from broadcast TV (terrestrial digital broadcast), and the unit will shut down.

Solution: We corrected the MICON Software so that no malfunction occurs.

MODIFICATION: Please refer to page 25 "**8.WRITING AND UPDATE SOFTWARE**" in Service Manual.

Parts:

Part Number of software:

SR6004MAIN: **SR6004_00M27DW499A06.zip** (Ver. V1006291) for SR6004

SR5004MAIN: **SR5004_00M26DW499A06.zip** (Ver. V1006291) for SR5004

Serial Number Range:

Please apply the above modification to the production models in the following serial numbers.

All Units

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.