



Service Bulletin

No.: MZ02-016

Date: December 4, 2006

Model: SR5200, SR6200, SR7200

Subject: The problem that No sound is out put when AUDIO signal is changed from AC-3 to PCM.

Symptom: When the SET is connected to a DVD Player (DV4200, DV6200, VC5200) no sound is out put when the AUDIO signal is changed from AC-3 to PCM.

Solution: Replace MICRO PROCESSOR (OPT) IC107 on the MAIN CIRCUIT BOARD.

Parts:

Ref#	Description	Part Number
IC107	CXP7400P100-1 QFP	*HU100600R

Serial Number Range:

The countermeasure applies only to this type of problem.