



Service Bulletin

No.: MZ10-040

Date: September 15, 2010

Model: SR7005

Subject: Issuing of the initial firmware for DFW (D&M Firmware Writer).

This is Information.

Reason: Regional service needs the initial firmware.

Solution: METHOD OF UPDATE: firmware update via RS232C. We will supply the following program files for updating the subject models. Please refer to the following Instruction Manual for the updating procedure.

DFW software:

DFW_0005_SR7005_(Rev.1.0.13).exe: Firmware Update Program **DFW_0005_SR7005_Rev.1.0.13_Manual_EN.pdf:** Instruction Manual for Firmware Update.

Firmware:

SR7005_U_N_F_K_MZ10-040.zip

	Name	Version
1	Main	83.47
2	Main FBL	00.10
3	Sub	27.17
4	Sub FBL	05.01
5	DSP	60.06
6	Audio PLD	05.02
7	OSD CFG	200912070011
8	OSD PRG	201006111006
9	OSD DAT	201006111008
10	OSD DAT	201003090106

	Name	Version
11	DM860	201002081213
	SBL	
12	DM860	201007020024
	IMG(U)	
13	DM861	201006220802
	IMG(N)	
14	DM862	201007080105
	IMG(F)	
15	DM863	201007080059
	IMG(K)	

Serial Number Range:

Αl