

marantz[®]

Service Bulletin

No. : MZ07-036


Date: March 19, 2007

Model: SR7001, SR8001

Subject: Correction of the Service Manual, PACKING (Accessories) parts list.

Symptom: The MICROPHONE part number mentioned on the SR7001/SR8001's Service Manual is incorrect. (Service Manual page 134 or 135)

Solution: Use the (MJI) part number listed in the Parts section when ordering a replacement Microphone.



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

Parts:

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (FOR EUR)	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	-		00M05CW009010	00M05CW009010	MICROPHONE	MIC AUDYSSET Ferrite Core is not included Factory code no. CMICROSR8001
NEW	-		90M-ZK000670R	90M-ZK000670R	MICROPHONE	MIC AUDYSSET Ferrite Core is included Factory code no. CMICROSR8001A

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.