

marantz® SERVICE BULLETIN		Date: 16-July-2002	Model: PM8200,PS17, SR8200,SR9200
		Page: 1/1	REF.NBR: MZ02-013
Circulation:		Subject:	
Application:		In correct a RELAY part was used.	
x for information customer complaint in case of service mandatory			
		See Below	

[PHENOMENON]

Incorrect parts mixed and were used.

[SOLUTION]

Please exchange for the correct the part.

Correct part no **9965 000 05895** (PCS part no)

LY20240490 (MJI part no)

Correct part 24VDC
Incorrect part 12VDC



POS.NO.	PCB name	Service manual
PM8200 L701	P101-MAIN CIRCUIT BOARD	page 9 and page 10
PS17 LB03/ LB04	PB04-BACK UP SUPPLY CIRCUIT BOARD	page32
SR8200 LP91	P124-SPK OUTS FRONT SURRBACK HEAD CIRCUIT BOARD	page71
SR9200 LP91	P124-SPK OUTS FRONT SURRBACK HEAD CIRCUIT BOARD	page71

[REMARKS]

There is no problem in the usual use condition , replace a part when it is returned by the repair.

< Application is limited to the following LOT number >

PM8200/N1B/N1G	07	LOT
PS17/S1G	09	LOT
SR8200/U1B/U1G	02-03	LOT
SR8200/S1G	03-04	LOT
SR9200/U1B/S1G	04	LOT

The Lot number and service modification code is mentioned the serial number label on the rear panel.
(ex. **MZxxxxxx07xxxx**)

Approved by **M.KIMURA**

Written by **S.NAGAO**