



Service Bulletin

No. : MZ08-033

Date: April 24, 2008

Model: SR9600

Subject: Service spare part addition/deletion information

Symptom:

1. The part number of IC (**POS.NO. QO02**) on the 1394 PWB is no longer available as a repair part. This IC cannot be replaced with a new one because you cannot write-in the ID and device key for IEEE1394.
2. The part number of 1394 PWB ASSY was added to Service spare part.

Solution:

The following part number was added / deleted.

	PAGE	POS. NO.	PART NO. (MZ)	PART NAME	DESCRIPTION
DELETE	281	QO02	80M11AJA00201	U-PRO	M29W800DT70N1 1394 FLASH
ADD	209	PV24	88M12AJ610001	PWB ASSY	1394 PWB ASSY

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.