
MODIFICATION

PROBLEM:

The problems caused can be various. No output or distortion in sound can be one of them.

CAUSE:

The polarity of the capacitor C222 is given wrong on the PCB, therefore the insertion is done wrong.

SOLUTION:

Remove the capacitor (replace if necessary) and mount the capacitor again with the + marking to the - marking of the PCB

PRODUCTION:

This modification will be implemented in the production.

This modification should be made when you have a 514 in for service.

Special thanks to AudioNord Danmark for supplying this information