

## **Circuit Change**

---

---

***PROBLEM:*** Resistor is overheating.

---

***CAUSE:*** Resistor R443 is underrated.

---

***SOLUTION:*** Change R443 from 560R 1/4W fusible resistor to 560R 1W fusible resistor.

---

### ***PRODUCTION:***

This change has been implemented in production from serial number:

---

#### **Contact:**

**NAD Electronics International  
633 Granite Court  
Pickering, ON Canada L1K 3K1  
Voice: 905-831-0799 FAX 905-837-6357  
NAD@www.NADelectronics.com**