

## **Circuit Change**

---

---

***PROBLEM:*** *It is possible that recently delivered S500I product has incorrect fuse type fitted .*

---

***CAUSE:*** *It is a fast blow instead of a slow blow time delay fuse which may be present.*

---

***SOLUTION:*** *To prevent premature fuse failure please change the incorrect fuse to the correct fuse. The current and voltage rating is the same. See below for correct type.*

*Incorrect type - F250mA 250v or 250mA 250v*

*Correct type - T250mA 250v (Time Delay/Slow Blow)*

---

**Contact:**

**NAD Electronics International  
633 Granite Court  
Pickering, ON Canada L1K 3K1  
Voice: 905-831-0799 FAX 905-837-6357  
[www.nadelectronics.com](http://www.nadelectronics.com)**