

## Service Information T750

## **Circuit Change**

PROBLEM: You may receive a complaint about noise coming from any or all speakers. The noise is like a whining sound often varying in frequency.

The power supply capacitors in the rear channel section can deteriorate with time.

SOLUTION: Replace capacitors C924 and C925, 4700 uF/35v on the rear channel board.

## **Contact:**

**NAD Electronics International 633 Granite Court** Pickering, ON Canada L1K 3K1 Voice: 905-831-0799 FAX 905-837-6357

www.NADelectronics.com