

BULLITIN FOR WARRANTY SERVICE STATIONS:

DATE: MAY 25, 1977

TO: ALL SERVICE TECHNICIANS

FROM: NATIONAL SERVICE MANAGER

SUBJ: Replacement of DCvoltage regulator

transistor @SD235 (Q801) for models 3035,5055, 6065 and (Q803) for models

7075 and 8085.

Due to power regulator transistor 2SD235 damage, we sugest that you use 2SC789 power transistor as a direct replacement.

Thank you,

Les Aubin

National Service mgr.

cc. Chief Engineer, Henry Itsuno

www.hifiengine.com