



18 Parkway, Upper Saddle River, NJ 07458

Date: 04/10/03

Model: TX-SR600

Ref: TXSR600PHASE

Symptom: When performing IN and OUT of speaker phase test from THX speaker setup disk, some receivers may exhibit improper function of surround and surround back speakers output.

Cause: Improper data management by IC Q702 S-Ram Chip

Solution: Replace Q702.

Part Number # 22241795R3 or

22241817R3