D&M
D&M Holdings Inc.
100 Corporate Drive Mahwah, NJ 07430

marantz®

Service Bulletin
No. : MZ06-016
Date: December 19, 2006

_____

Model: ST7001/U1B

Subject: Software Update Information.

Symptom: Improvement of RS232C specifications. It's demanded from CI installer. (Specifications change by latest Crestron system.)

Solution: 1. Update Software (firmware) version to [MP002].
Please refer to the service manual ST7001 page 3 to 9 for the procedure.

Before updating, please check the firmware version. It can be confirmed on the "B.SERVICE MODE". Please refer to the service manual ST7001 on page 3 for the procedure.

_____

<u>Attention:</u> Don't update with the zipped (XXX.zip) file. Please copy it on your PC first and unzip it before using it.

Parts:

Ref#	Description	Part Number
NA	Application Software	FMC8FX.zip
NA	Writing data "st7001xm mp002.mhx" for Ver.MP002	ST7001_Ver_MP002.zip

Serial Number Range:
This problem applies to the following serial number range.
ST7001/U1B: Applies to MZ000551000225 and earlier.
This improvement has been done in production from serial number MZ0005xx000224 and later.