D&M
D&M Holdings Inc.
100 Corporate Drive Mahwah, NJ 07430

marantz®

Service Bulletin
No. : MZ07-080
**Date:** August 21, 2007

_____

Model: ES7001

Subject: Correction of page 28 of the Service Manual.

Symptom: "Download Firmware for CPU (Mode 3)" mentioned in the ES7001's Service Manual is incorrect.

Solution: Download Firmware for CPU (Mode 3)" mentioned on Page 28 of the service manual was changed.

12. Click **other files...** from Firmware program file.

12. Firmware program file内の**other files...**をクリックします。

13. Choose **ES7001_QU01_Ver1.mot**. And click **Open**.
   NOTE : Version number changes whenever software released.

13. **ES7001_QU01_Ver1.mot**を選択し、**Open**をクリックします。
   注意：ソフトウェアの発行のたびにバージョンは変更されます。