

Date	Ref. No.	Model	
23.04.03	03AH002	CX-LEM50, CX-LEM51, XR-EM50, XR-EM51	TD
Subject			IRIS
Part number for "J231"			

SYMPTOM

Page 8 of the Service Manual lists incorrect information for the headphone jack J231 on the Key Board.

SOLUTION

The correct information for J231 is listed in the table below.

<i>Ref.</i>	<i>Description</i>	<i>Incorrect part number</i>	<i>Correct part number</i>
J231	Jack, Headphone	87-099-816-010	S2-3B0-292-000
		U-0150-132-U	U-0023-247-U