



AIWA CO.,LTD

UTSUNOMIYA FACTORY

2620, TOKUJIROU-MACHI, UTSUNOMIYA-SHI, TOCHIGI 321-21, JAPAN

SERVICE TECHNICAL INFORMATION

ONE POINT REPAIR

UTSUNOMIYA, SEPTEMBER 15, 1996

REF. NO. : SI-96-029

CUSTOMER RELATIONS & SERVICE DIV.

MODEL : HS-JX749
SUBJECT : New carrying case

CONTENTS : The hook of the HS-JX749 carrying case is located directly above the LCD, and has on occasion broken the LCD. Therefore, a new carrying case with the hook in a different position is now available. If the LCD has been broken due to the hook position, exchange the carrying case when making repairs.

* This remedy has been performed for models as of the March '96 production lot.

Part No.	Part Name	Ref. No.
84-HJ9-951-110	CARRYING CASE	—