

SERVICE TECHNICAL INFORMATION

ONE POINT REPAIR

UTSUNOMIYA, DECEMBER 30, 1997
REF. NO.: SI-97-059
CUSTOMER RELATIONS & SERVICE DIV.

- MODEL S : XR-AKH100, NSX-KH9, AKH8
SUBJECT : The laser pickup is always on.
DESCRIPTION : During the CD function, it is found that the laser pickup is always on regardless of CD STOP.
When repairing the aforementioned models, take the following countermeasures.
REMEDIES : 1) Remove R223 shown in the circuit diagrams (CD MAIN C.B) indicated below.
2) Short the patterns on both sides of R223.

