



- 4. ADDED AS SECONDARY OPERATION.
- 2. ALL CAPACITORS IN MICROFARADS, EXCEPT AS NOTED.
- 1. ALL RESISTORS IN OHMS

NOTES: UNLESS OTHERWISE SPECIFIED.

| | |
|--|--------------------------|
| CARVIN | |
| 12340 World Trade Drive San Diego, CA 92128 (858) 487-1600 FAX 487-6629 | |
| BR120 <i>System Master</i> | |
| DRAWN BY: GEORGE DREYER | DATE: 26SEPT05 |
| APPROVED: | DATE: |
| PCB NO: 30-42120 | REV: B |
| ASSY. NO: 80-42120 | REV: B |
| REVISED BY: GEORGE DREYER | DATE: 2ARL06 |

Changes from Assembly Rev (A).
Proto corrections: -15V via grounded, R257 grounded, Locational errors D11 moved up; added R11.

SMT SCREEN HOLES
#690 #689