



(X07-2590-11) (A/7) Note : Set input level to minimum before power on.






DESTINATION COUNTRY		UNIT No.	F2	F3.4	F5	J3	S11	W63	WH5	CN11-13	R110
ABB.	ABB.				YES/NO	YES/NO	NO	YES	YES	YES	YES
U.S.A.	PX	X07-2890-11	2A 125V	2.5A 125V	YES	4P	NO	NO	YES	YES	YES
GENERAL MARKET	M	X07-2890-21	T1.6A L 250V	T1.6A L 250V	NO	8P	YES	NO	NO	NO	NO
MALAYSIA	I										
U.K.	T										
EUROPE	E	X07-2892-71	T1.6A L 250V	T1.6A L 250V	NO	4P	NO	NO	NO	NO	NO
RUSSIA	Q										



- 2SA992(F/E)
- 2SC1845(F/E)
- 2SC4137F50(V,W)
- 2SC2493
- 2SB1624
- 2SC1740S(Q,R) or 2SC2785(F/E)
- 2SC2003(L,K)
- 2SC3940(R,S)
- UN4119 or DTA113ZSA
- BU2090
- SS131 or HSS104A
- NTZ115(B) or UZ-185SB
- NTZ111(B) or UZ-185B
- 3S686B or ISR139-400
- D3SBA20F03 or RBV-402LFA
- 530-2468-05
- 530-2490-05

- O1-4,21
- O7,8,11,12,19,20,24
- O8,10
- O15,16
- O17,18
- O22,27
- O23
- O25
- O26
- IC1
- D11,2,7,8,11,15,17,20,35
- D3,4
- D5,6
- D9
- D10
- D16
- D81-37
- D38



(M, L) TYPE
X05-CN1

1-4

A

(T, E) TYPE
X05-CN1

2-4


B

(Q) TYPE
X04-CN4

2-4

C

(X11-370X-XX) (A/3)



To
X07
(A-HS)

